

CERTIFICATE



This is to certify that

PIX TRANSMISSIONS LIMITED

PIX[®]

Mixing Plant
Nagalwadi, Hingna
Nagpur - 440 016
Maharashtra
INDIA

with the organizational units/sites as listed in the annex

has implemented and maintains a **Quality Management System**.

Scope:
Mixing of Rubber Compound.

Through an audit, documented in a report, it was verified that the management system fulfills the requirements of the following standard:

ISO 9001 : 2008

Certificate registration no.	503287 QM08
Excerpt from certificate registration no.	503289 QM08
Date of original certification	2014-06-13
Date of revision	2017-05-01
Date of certification	2016-06-08
Valid until	2018-09-14



DQS Inc.

Brad McGuire
Managing Director

